

PROPOSAL #20000536 - FIRE EXTINGUISHER SERVICE & REPAIR

CINTAS FIRE PROTECTION

Description	Approx. Qty	Inspect Cost	Recharge Cost	Replace Cost
5# CO2	54	\$ 3.00	\$ 30.00	\$ 150.00
10# CO2	1	\$ 3.00	\$ 30.00	\$ 220.00
15# CO2	38	\$ 3.00	\$ 35.00	\$ 260.00
20# CO2	40	\$ 3.00	\$ 35.00	\$ 270.00
2 1/2# ABC	38	\$ 3.00	\$ 25.00	\$ 32.00
10# ABC	52	\$ 3.00	\$ 30.00	\$ 81.00
20# ABC	59	\$ 3.00	\$ 36.00	\$ 152.00
5# HALON	1	\$ 3.00	\$ 40.00	\$ 200.00
9# HALON	2	\$ 3.00	\$ 72.00	\$ 393.00
10# DRY CHEMICAL	8	\$ 3.00	\$ 30.00	\$ 30.00
GAUGE	24			\$ 10.00
PULL PINS	24			\$ 1.50
WALL BRACKETS	24			\$ 8.00
HMS LABELS	24			\$ 1.00
NOZZLES	24			\$ 12.00
O-RING	24			\$ 2.00
CO2 VALVE HEAD	24			\$ 14.00

Hydro Testing Charge Per Cylinder	\$ 9.00
--------------------------------------	---------

SUMMIT COMPANY

Description	Approx. Qty	Inspect Cost	Recharge Cost	Replace Cost
5# CO2	54	\$ 1.50	\$ 20.00	\$ 152.25
10# CO2	1	\$ 1.50	\$ 22.00	\$ 252.00
15# CO2	38	\$ 1.50	\$ 25.00	\$ -
20# CO2	40	\$ 1.50	\$ 30.00	\$ -
2 1/2# ABC	38	\$ 1.50	\$ 14.00	\$ 48.00
10# ABC	52	\$ 1.50	\$ 30.00	\$ 98.00
20# ABC	59	\$ 1.50	\$ 40.00	\$ 168.00
5# HALON	1	\$ 1.50	\$ 164.75	\$ -
9# HALON	2	\$ 1.50	\$ 278.15	\$ -
10# DRY CHEMICAL	8	\$ 1.50	\$ 30.00	\$ 98.00
GAUGE	24			\$ 5.00
PULL PINS	24			\$ -
WALL BRACKETS	24			\$6.00 TO \$15.00
HMS LABELS	24			\$ -
NOZZLES	24			\$7.00 TO \$15.00
O-RING	24			\$4.00 EXT & \$9.00 CO2
CO2 VALVE HEAD	24			\$96.00 - \$119.00

Hydro Testing Charge Per Cylinder	\$ 75.00
--------------------------------------	----------